



Ticket Number: 601472354

GENERAL INFORMATION

Dig Number 601472354

Dig Date Nov 27, 2023 08:00 am

Status Acknowledged

LOCATION INFORMATION

Address 531 - 535 W 44TH ST

Placement CURBLANE,PARKWAY,SIDEWALK,TRAFFIC

DETAILS

Requested 11/20/2023 1:10 pm
(NOTE: Dig Ticket is voided if work does not commence before Dec 04, 2023.)

Final Day of Ticket Validity 12/18/2023

Depth of Excavation 1 feet

Expected Duration N/A

Associated Permit Number DOT1893601

Permittee Name DWM

Work on? Public right-of-way

Location Specific Facility Info Yes

Routing Type Automatic

Onsite Contact Name Aribel Rosales

Onsite Contact Phone Number (708)333-1300

Amended Dig Notice? Yes

Type of Work Saw cutting for DWM

Work will use

Location of Dig

Activity Comment

APPLICANT DETAILS

Contact Name SANCHEZ PAVING Company Inc*

Contact Address 16309 SOUTH CRAWFORD AVE MARKHAM, IL 60428

Contact Phone (708)333-1300

Contact Email aribel@sanchezpaving.net

Additional Email Addresses aribel@sanchezpaving.net

NOTICE HISTORY								
Utility Name	Site ID	Notice ID	Type	Status	Created		Last Status Time	
Peoples Gas Central and South	79	18596509	Initial	Marked	11/20/2023	7:53:58 PM	11/22/2023	1:32:02PM
City of Chicago (CoC)	22	18596508	Initial	Ack	11/20/2023	7:53:58 PM	11/20/2023	8:19:57PM
AT&T (SBC IL)*	70	18596512	Initial	Ack	11/20/2023	7:53:58 PM	11/20/2023	8:01:35PM
Peoples Gas*	136	18596511	Initial	Ack	11/20/2023	7:53:58 PM	11/20/2023	8:13:48PM
ComED South	5	18596513	Initial	Ack	11/20/2023	7:53:58 PM	11/20/2023	8:03:16PM
Rogers Telecom/Gabe's Technical Service	42	18596510	Initial	Ack	11/20/2023	7:53:58 PM	11/20/2023	8:15:48PM

REVISION HISTORY				
Rev #	Date		User	Reason
4546123	11/20/2023	1:10:02 PM	Sanchez1300	Created
4547286	11/20/2023	7:54:00 PM	GLENNPURRY	Approved
4547324	11/20/2023	7:53:29 PM	GLENNPURRY	Updated

LOCATION SPECIFIC FACILITY INFORMATION		
Utility Name	Site ID	Additional Notes
Peoples Gas Central and South	79	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.