



REVISION

Ticket Number: 601498216
Revision Number: 4637720

GENERAL INFORMATION

Dig Number 601498216
Dig Date Feb 08, 2024 01:15 pm
Status Unacknowledged

LOCATION INFORMATION

Address 200 - 236 N LAVERGNE AVE
Placement SIDEWALK,PARKWAY

DETAILS

Requested 2/6/2024 11:29 am
 (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.)
Final Day of Ticket Validity 3/5/2024
Depth of Excavation 2 feet
Expected Duration 1
Associated Permit Number DOT1903662
Permittee Name JOHN BURNS CONSTRUCTION CO.*
Work on? Public right-of-way
Location Specific Facility Info Yes
Routing Type Automatic
Onsite Contact Name Peter
Onsite Contact Phone Number (773)794-9999
Amended Dig Notice? No
Type of Work Saw Cutting
Work will use
Location of Dig
Activity Comment

APPLICANT DETAILS

Contact Name COBRA CONCRETE CUTTING SERVICE
Contact Address 2416 E OAKTON ARLINGTON HEIGHTS, IL 60005
Contact Phone
Additional Email Addresses mattrichard@cobraconcrete.com

NOTICE HISTORY								
Utility Name	Site ID	Notice ID	Type	Status	Created		Last Status Time	
City of Chicago (CoC)	22	44253647	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
AT&T (SBC IL)*	70	44253651	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
Peoples Gas Central and South	79	44253649	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
Peoples Gas*	136	44253650	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
ComED South	5	44253652	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
AT&T Local^	11	44253648	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM
CROSSTOWN FIBER*	226	44253653	Initial	UnAck	2/6/2024	1:08:30 PM	2/6/2024	1:08:30PM

REVISION HISTORY				
Rev #	Date		User	Reason
4637720	2/6/2024	1:08:32 PM	tmorris	Approved
4637726	2/6/2024	1:08:16 PM	tmorris	Updated
4637452	2/6/2024	11:29:19 AM	MKustra	Created

LOCATION SPECIFIC FACILITY INFORMATION		
Utility Name	Site ID	Additional Notes
Peoples Gas Central and South	79	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.