



REVISION

Ticket Number: 601509222

Revision Number: 4670183

GENERAL INFORMATION

Dig Number 601509222

Dig Date N/A

Status

LOCATION INFORMATION

Address 3500 - 3558 N KENNEDY EXPY

DETAILS

Requested 3/4/2024 11:37 am

(NOTE: Dig Ticket is voided if work does not commence before Mar 18, 2024.)

Final Day of Ticket Validity

Depth of Excavation 2 feet

Expected Duration 3

Permittee Name

Work on? Private Property

Location Specific Facility Info No

Routing Type Automatic

Onsite Contact Name Lisa Dixon

Onsite Contact Phone Number (708)728-1895

Amended Dig Notice? No

Type of Work

PAVEMENT SAW CUTTING

Work will use

Location of Dig LOCATE THE EXPRESS LANES THAT ARE INTERCHANGED BETWEEN INBOUND AND OUTBOUND ON THE KENNEDY EXPRESSWAY

Activity Comment LOCATE THE EXPRESS LANES THAT ARE INTERCHANGED BETWEEN INBOUND AND OUTBOUND ON THE KENNEDY EXPRESSWAY

Extension Comments
05/13/2024 - STILL WORKING IN THE AREA
04/18/2024 - STILL WORKING IN THE AREA
03/26/2024 - STILL WORKING IN THE AREA

APPLICANT DETAILS

Contact Name QUALITY SAW AND SEAL INC.

Contact Address 7600 WEST 79TH ST. BRIDGEVIEW, IL 60455

Contact Phone (708)728-1895

Additional Email Addresses ldixon@qualitysawandseal.com

NOTICE HISTORY						
Utility Name	Site ID	Notice ID	Type	Status	Created	Last Status Time

REVISION HISTORY			
Rev #	Date	User	Reason
4701241	3/26/2024 1:48:21 PM	Idixon	Remark
4670616	3/4/2024 2:41:52 PM	GLENNPURRY	Approved
4670183	3/4/2024 11:37:01 AM	Idixon	Created
4670641	3/4/2024 2:41:12 PM	GLENNPURRY	Updated
4733640	4/18/2024 11:12:55 AM	Idixon	Renew
4773107	5/13/2024 11:44:40 AM	Idixon	Remark
4701262	3/26/2024 1:48:06 PM	Idixon	Renew
4773053	5/13/2024 11:44:25 AM	Idixon	Renew
4733650	4/18/2024 11:13:11 AM	Idixon	Remark