



REVISION

Ticket Number: 601556232
Revision Number: 4812443

GENERAL INFORMATION

Dig Number 601556232
Dig Date Jun 10, 2024 08:00 am
Status Unacknowledged

LOCATION INFORMATION

Address 2211 N KEELER AVE

DETAILS

Requested 6/5/2024 10:48 am
 (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.)

Final Day of Ticket Validity 7/3/2024

Depth of Excavation 1 feet

Expected Duration 28

Associated Permit Number DOT1958659

Permittee Name G & V CONST CO INC (SL)

Work on? Public right-of-way

Location Specific Facility Info Yes

Routing Type Automatic

Onsite Contact Name Monica

Onsite Contact Phone Number (630)595-6474

Amended Dig Notice? No

Type of Work Sidewalk Replacement

Work will use
 Overhead Equipment
 Hydraulic Equipment

Location of Dig

Activity Comment

APPLICANT DETAILS

Contact Name G & V CONST CO INC (SL)

Contact Address 5239 W. DIVERSEY SUITE 201 CHICAGO, IL 60639

Contact Phone (773)417-8663

Contact Email ANGELA@GVCONSTRUCTIONCO.COM

Additional Email Addresses gvpermits@gmail.com

NOTICE HISTORY								
Utility Name	Site ID	Notice ID	Type	Status	Created		Last Status Time	
Peoples Gas North	78	45841184	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM
AT&T (SBC IL)*	70	45841187	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM
Rogers Telecom/Gabe's Technical Service	42	45841185	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM
Peoples Gas*	136	45841186	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM
ComED North*	4	45841188	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM
City of Chicago (CoC)	22	45841183	Initial	UnAck	6/5/2024	9:42:20 PM	6/5/2024	9:42:20PM

REVISION HISTORY			
Rev #	Date	User	Reason
4810334	6/5/2024 10:48:21 AM	gvconst	Created
4812379	6/5/2024 9:41:00 PM	GLENNPURRY	Updated
4812443	6/5/2024 9:42:22 PM	GLENNPURRY	Approved

LOCATION SPECIFIC FACILITY INFORMATION		
Utility Name	Site ID	Additional Notes
Peoples Gas North	78	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.