

REVISION

Ticket Number: 601627998 **Revision Number:** 5038827

GENERAL INFORMATION						
Dig Number	601627998					
Dig Date	N/A					
Status						
	LOCATION INFORMATION					
Address	3101 - 3159 E 93RD ST					
Placement	PARKWAY,SIDEWALK					
	DETAILS					
Requested	ted 11/6/2024 4:12 pm					
	(NOTE: Dig Ticket is voided if work does not commence before Nov 20, 2024.)					
Final Day of Ticket Validity						
Depth of Excavation	7 feet					
Expected Duration	N/A					
Associated Permit Number	DOT1996522					
Permittee Name	RCN TELECOM SERVICES OF ILLINOIS INC (Astound)*					
Work on?	Public right-of-way					
Location Specific Facility Info	Yes					
Routing Type	Automatic					
Onsite Contact Name	Brian Rodriguez					
Onsite Contact Phone Number	(630)514-0637					
Amended Dig Notice?	No					
Type of Work	Digging Test Holes					
	Utility Construction conduit installation via open cut trench					
Work will use	Conduit installation via open out tienon					
Work will use	Hydraulic Equipment					
Location of Dig						
Activity Comment	Please mark and locate all applicable utilities beginning from the NE corner of 93rd & Baltimore.					
	Please going eastbound along the north side of 93rd st for approximately 250' until you reach the existing communications handhole that is next to the Crown Castle manhole.					
	APPLICANT DETAILS					
Contact Name	WESTERN UTILITY CONTRACTORS INC					
Contact Address	2565 PALMER AVENUE UNIVERSITY PARK, IL 60466					
Contact Phone	(708)235-1408					
Additional Email Addresses						
Additional Linan Addiesses	blodingdo2@westerndtility.com					

NOTICE HISTORY				
Utility Name	Site ID Notice ID	Type Stat	tus Created	Last Status Time

REVISION HISTORY					
Rev#	Date	User	Reason		
5038837	11/6/2024 4:26:08 PM	GLENNPURRY	Approved		
5038827	11/6/2024 4:12:28 PM	brianrod16	Created		

LOCATION SPECIFIC FACILITY INFORMATION				
Utility Name	Site ID	Additional Notes		
Peoples Gas Central and South	79	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.		