

REVISION

Ticket Number: 601658208 **Revision Number:** 5177434

omeago							
GENERAL INFORMATION							
Dig Number	601658208						
Dig Date	N/A						
Status	Status						
LOCATION INFORMATION							
Address 925 - 1001 S RACINE AVE							
DETAILS							
Requested	2/25/2025 2:02 pm						
	(NOTE: Dig Ticket is voided if work does not commence before Mar 11, 2025.)						
Final Day of Ticket Validity							
Depth of Excavation	2 feet						
Expected Duration	N/A						
Associated Permit Number	DOT2043748						
Permittee Name	BIGANE PAVING CO (CONSTRUCTION)*						
Work on?	Public right-of-way						
Location Specific Facility Info	Yes						
Routing Type	Automatic						
Onsite Contact Name	Juan Arreola						
Onsite Contact Phone Number	(773)447-8540						
Amended Dig Notice?	No						
Type of Work	Sewer adjustments & Remove and Replace sidewalk, curb, driveways						
Work will use							
Location of Dig	Right of way to Right of way						
Activity Comment							
Extension Comments	05/27/2025 - ongoing work 05/05/2025 - ongoing work 04/11/2025 - ongoing work 03/21/2025 - ongoing work						
	APPLICANT DETAILS						
Contact Name	HUMIR CONSTRUCTION, INC.*						
Contact Address	4632 SOUTH KOMENSKY CHICAGO, IL 60632						
Contact Phone	(773)475-4500						
Additional Email Addresses	humirconstruction@yahoo.com						

NOTICE HISTORY					
Utility Name	Site ID Noti	ice ID Type	Status	Created	Last Status Time

REVISION HISTORY					
Rev#	Date	User	Reason		
5177434	2/25/2025 3:59:16 PM	Kay6Jones	Updated		
5235674	4/11/2025 2:24:46 PM	Humir19	Renew		
5207001	3/21/2025 1:01:45 PM	Humir19	Renew		
5177417	2/25/2025 3:59:25 PM	Kay6Jones	Approved		
5177133	2/25/2025 2:03:03 PM	Humir19	Created		
5260189	4/29/2025 2:41:47 PM	Humir19	Remark		
5297981	5/27/2025 1:45:47 PM	Humir19	Renew		
5267845	5/5/2025 10:16:26 AM	Humir19	Renew		

LOCATION SPECIFIC FACILITY INFORMATION					
Utility Name	Site ID	Additional Notes			
Peoples Gas Central and South	79	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.			