

REVISION

Ticket Number: 601505632 **Revision Number:** 4660407

Dig Number Dig Number Dig Namber Dig Date N/A Status LOCATION INFORMATION Address 400 W 57TH ST DETAILS Requested (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation Expected Duration 1 Permittee Name Work on? Location Specific Facility Info Routing Type Automatic Onsite Contact Name Onsite Contact Hone Number Amended Dig Notice? Type of Work Soil Borings Work will use Hydraulic Equipment Location of Dig Activity Comment Routing Is located at street level Activity Comment WANG TESTING SERVICES, INC* Contact Name (600) ERSTING SERVICES, INC* Contact Phone Whan ST LOMBARD, IL 60148 Contact Phone I Nathan Davis Good Service Services Servic							
Dig Date Status Status LOCATION INFORMATION Address 400 W 57TH ST DETAILS Requested 2/23/2024 9:42 am (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info 79	GENERAL INFORMATION						
LOCATION INFORMATION	Dig Number	601505632					
Address 400 W 57TH ST DETAILS Requested 2/23/2024 9:42 am (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Automatic Onsite Contact Name Nathan Davis Onsite Contact Name (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Dig Date	N/A					
Requested (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Soil Borings Work will use Boring Equipment Hydraulic Equipment Location of Dig Activity Comment ROW. Boring is located at street level Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavs@wangtesting.com	Status						
Requested 2/23/2024 9:42 am (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Automatic Onsite Contact Name Nathan Davis Onsite Contact Name (815)370-4841 Amended Dig Notice? No Type of Work Will use Boring Equipment Hydraulic Equipment Location of Dig Activity Comment ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	LOCATION INFORMATION						
Requested (NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Nosite Contact Name Nathan Davis Onsite Contact Name (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Contact Soft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Address	400 W 57TH ST					
NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.) Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1	DETAILS						
Final Day of Ticket Validity Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Yes Routing Type Automatic Onsite Contact Name (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Coation of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Requested	2/23/2024 9:42 am					
Depth of Excavation 60 feet Expected Duration 1 Permittee Name Work on? Private Property Location Specific Facility Info Yes Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com		(NOTE: Dig Ticket is voided if work does not commence within 14 days of ticket creation.)					
Expected Duration Permittee Name Work on? Private Property Location Specific Facility Info Yes Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Contact Name Now Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Final Day of Ticket Validity						
Permittee Name Work on? Private Property Location Specific Facility Info Yes Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Depth of Excavation	60 feet					
Work on? Private Property Location Specific Facility Info Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Expected Duration	1					
Location Specific Facility Info Yes	Permittee Name						
Routing Type Automatic Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Work on?	Private Property					
Onsite Contact Name Nathan Davis Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Location Specific Facility Info	Yes					
Onsite Contact Phone Number (815)370-4841 Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Location of Dig Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Routing Type	Automatic					
Amended Dig Notice? No Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Onsite Contact Name	Nathan Davis					
Type of Work Soil Borings Work will use Boring Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Onsite Contact Phone Number	(815)370-4841					
Work will use Boring Equipment Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Amended Dig Notice?	No					
Hydraulic Equipment Location of Dig Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 nathandavis@wangtesting.com	Type of Work	Soil Borings					
Activity Comment Locate 50ft radius around painted soil boring B-05 within 50ft west of Norfolk Southern Railroad ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Work will use						
ROW. Boring is located at street level APPLICANT DETAILS Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Location of Dig						
Contact Name WANG TESTING SERVICES, INC* Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Activity Comment	,					
Contact Address 1126 N MAIN ST LOMBARD, IL 60148 Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com		APPLICANT DETAILS					
Contact Phone (630)519-4247 Contact Email nathandavis@wangtesting.com	Contact Name	WANG TESTING SERVICES, INC*					
Contact Email nathandavis@wangtesting.com	Contact Address	1126 N MAIN ST LOMBARD, IL 60148					
	Contact Phone	(630)519-4247					
Additional Email Addresses Nathandavis@wangtesting.com	Contact Email	nathandavis@wangtesting.com					
	Additional Email Addresses	Nathandavis@wangtesting.com					

NOTICE HISTORY					
Utility Name	Site ID Notice ID	Type	Status	Created	Last Status Time

REVISION HISTORY					
Rev#	Date	User	Reason		
4666270	2/28/2024 2:58:45 PM	davisn	Remark		
4660318	2/23/2024 11:22:03 AM	Jehovah1	Approved		
4660407	2/23/2024 11:21:50 AM	Jehovah1	Updated		
4660169	2/23/2024 9:42:40 AM	davisn	Created		

LOCATION SPECIFIC FACILITY INFORMATION					
Utility Name	Site ID	Additional Notes			
Peoples Gas Central and South	79	Warning! Peoples Gas has buried critical facilities in or near the area of your locate request and may need to have a representative present when you excavate.			