

**HIT REPORTED**

Utility Hit in Public Right of Way

Ticket Number: 601126101**GENERAL INFORMATION****Hit Report Number** 601126101**Hit Report Date** 1/26/2022 8:10:00 AM**Status** No Notices**LOCATION INFORMATION****Address** 5927 N HERMITAGE AVE**DETAILS****Related Dig Ticket Number** 601076685**Requested** 1/26/2022 2:16 PM**Excavation Depth** 5**Hit in public right-of-way?** Yes**Facility Owner****Parent Case Number** DOT_HR21218**Dig Location** Public way**Facility Hit** UNKNOWN**Location specific facility information** No**Permit Number****CONTACTS****Onsite Contact Name** Michael Diaz**Onsite Contact Phone Number** (773)597-5080**Onsite Contact Email** mikey@goodeplumbing.com**Hit By Name** GOODE PLUMBING***Hit By Phone Number** (773)930-3451**Hit By Address** 5129 PEARL ST SCHILLER PARK, IL 60176**Reported By Name** John Brooks**Reported By Phone Number** (312)743-1414**Reported By Address** 445 N SACRAMENTO BLVD CHICAGO, IL 60612**Restored By Name****Restored By Phone Number****Restored By Address** ,**Restored Date Time**

NOTICE HISTORY						
Utility Name	Site ID	Notice ID	Type	Status	Created	Last Status Time

REVISION HISTORY			
Rev #	Date		Reason
3314319	1/26/2022	2:16:43 PM	Created
3314403	1/26/2022	2:19:01 PM	Updated