

**HIT REPORTED**

Utility Hit in Public Right of Way

Ticket Number: 601398308**Revision Number:** 4288147**GENERAL INFORMATION****Hit Report Number** 601398308**Hit Report Date** 7/19/2023 3:14:00 PM**Status** Unacknowledged**LOCATION INFORMATION****Address** 5120 W 44TH ST**DETAILS****Related Dig Ticket Number** 601343456

Dig Location WHILE DIGGING NEXT TO THE SIDEWALK FOUND THE EDGE OF COMED VAULT DAMAGED ABOUT 1 FT DOWN. ENGINEER PAT SHEDDY MACHINE # WS988R THIS HAPPENED AT APPROX. 130PM.NOTIFIED COMED .
Hit occurred outside the area specified by the related Dig Ticket.

Facility Hit COMED CABLE & CONDUIT**Location specific facility information** No**Permit Number****Requested** 7/19/2023 3:29 PM**Excavation Depth** 1**Hit in public right-of-way?** Yes**Facility Owner** ComED South**CONTACTS****Onsite Contact Name** JOHN TREVSA**Onsite Contact Phone Number** (630)470-2115**Onsite Contact Email** SONYA.MORA@CITYOFCHICAGO.ORG**Hit By Name** City of Chicago DWM**Hit By Phone Number** (312)744-7017**Hit By Address** 1000 E. OHIO STREET CHICAGO, IL 60611**Reported By Name** City of Chicago DWM**Reported By Phone Number** (312)744-7017**Reported By Address** 1000 E. OHIO STREET CHICAGO, IL 60611**Restored By Name****Restored By Phone Number****Restored By Address****Restored Date Time**

NOTICE HISTORY								
Utility Name	Site ID	Notice ID	Type	Status	Created		Last Status Time	
ComED South	5	40250826	Initial	UnAck	7/19/2023	3:25:29 PM	7/19/2023	3:25:29PM

REVISION HISTORY				
Rev #	Date		User	Reason
4288580	7/19/2023	6:04:11 PM	lindabudz	Updated
4304283	7/26/2023	2:10:24 PM	399152	Updated
4288143	7/19/2023	3:21:25 PM	Smora09	Created
4288147	7/19/2023	3:25:33 PM	lindabudz	Approved
4486655	10/18/2023	10:10:50 AM	382237	Complete